

Tuesday 15 August 2023

OIA IRO-456

Name:

Email: @yahoo.co.uk

Kia ora

Official information request regarding water leak at 8a Frobisher Street.

Thank you for your official information request (OIA IRO-456) dated Tuesday 2 May 2023. You requested all documentation and records relating to the investigation which determined there was a leak on both yours and your neighbour's property, as well as any records, maps, or diagrams of service connections.

We have considered your request in accordance with the Local Government Official Information and Meetings Act 1987 (the Act) and determined that we are able to grant your request in part.

Please see in our email to you the Service Request data and a Certification to Subdivide. Pursuant to Section 7(2)(a) of the Act some information has been redacted as it is personal about private individuals. In accordance with Section 7(2)(b)(ii) of the Act, we are withholding costing information within the certification document due to commercial sensitivity.

We sincerely apologise for the time is has taken to provide you with a response.

You have the right to seek an investigation and review by the Ombudsman of this decision. Information about how to make a complaint is available at www.ombudsman.parliament.nz or freephone 0800 802 602.

Ngā mihi,

Acting Group Manager, Customer Operations Group

For the latest news and updates, follow us on our social channels:



/wellingtonwater



@wgtnwaternz & @wgtnwateroutage



@wellington_water

	. "				7			D	6 11' /6			
Address	Council Reference ID	Asset ID	Work Order Summary	Job Details	Mator	Priority	Status	The second secon	Completion/Closed Date	Entry Data	Work Log Summary	Work Log Datail
Address	Reference ID	Asset ID	work Order Summary	Job Details	Water 3 Frobishe		Status	Date	Date	Entry Date	work Log Summary	Work Log Detail
3 Frobisher Street, Island Bay, Wellington, 6023	WCCSR-218746	WCC_WW01936 7	Blockage 3 Frobisher Street, Island Bay, Wellington	Caller is a plumber and advised that there is a blockage in the council main at this address (they went down 14m and couldn't find it). Please attend and unblock.	Wastewater	1		8/13/2021 8:20:32 AM	8/13/2021 10:13:21 AM	8/13/2021 8:20:54 AM	Note from Council	Address: 3 FROBISHER STREET, Island Bay Open in Google Maps: https://www.google.com/maps/search/?api=1&query=-41.34366114838697,174.7623082169323
								<u> </u>		8/13/2021 8:36:54 AM	Spoke to caller	Spoke to the plumber who attended last night. Advised we'll attend. RICH TEXT
										8/13/2021 10:57:39 AM	Block sewer	Arrived on site we checked the wastewater main and found that it was blocked we proceeded to rod the line we road 2 rods inside the manhole and found that the blockage was inside the manhole and we cleared it we then tidy up and disinfect the effected area under the house all clean
										8/16/2021 10:36:58 AM	Note from Council	Closed by WCC
					3A Frobish	er Street					At a second of the second of t	
3A Frobisher Street, Island Bay, Wellington, 6023	WCCSR-396024	WCC_SW015423	Instructed Works 3A Frobisher Street, Island Bay	<div>22/11/22 CAR N/A no excavation </div> <div>Stormwater Inlet Location Request - 3A Frobisher Street Hello,</div>	Stormwater	4		6/10/2022 3:05:22 AM	11/17/2022 1:45:05 PM	6/10/2022 3:05:42 AM	Note from Council	Address: 3A FROBISHER STREET, Island Bay Open in Google Maps:
				Can we get some-one from Wellington Water to locate stormwater inlet (SW015423) as shown below in the pink circle at 3A Frobisher Street please? RICH TEXT								https://www.google.com/maps/search/?api=1&query=-41.343611598497596,174.76202798362166
						9				6/13/2022 1:40:44 PM	Assigned to	Assigned to . RICH TEXT
										6/13/2022 1:40:50 PM		
										6/26/2022 4:22:35 PM	Note from Council	Hi, Can you let me know if this has been actioned yet?
												Regards,
												Associate - Planning SpencerHolmes Limited
												PO Box 588, Wellington 6140 Level 10, 57 Willis Street, Wellington 6011 adg@spencerholmes.co.nz <mailto:adg@spencerholmes. co.nz=""> www.spencerholmes.co.nz<blocked::http: td="" www.spenc<=""></blocked::http:></mailto:adg@spencerholmes.>
	<u>J</u>		L	<u>.</u>	135	128	100	, ,	<u> </u>		<u>L</u>	WWW.spericernollies.co.iiz \blockediittp.//www.speric

<u> </u>						
						erholmes.co.nz/> P M M
						Please consider the environment before printing this email.
						This email message and any attachments should be treated as CONFIDENTIAL. If you are not the intended recipient, any use, disclosure or copying of this message or attachments is strictly prohibited. If you have received this email message in error please notify
						admin@spencerholmes.co.nz <mailto:admin@spencerho lmes.co.nz=""> immediately and erase all copies of the message and any attachments.</mailto:admin@spencerho>
				7/1/2022 3:42:28 PM	Further investigation required	Arrived onsite, Knocked on door but nobody was home, Went around the back deck and tried to search for the intake but couldn't find, More investigation required
				7/1/2022 3:42:29 PM	Status Change to PAUSE	Further investigation required
				7/13/2022 3:40:05 PM	Please pass to cctv	Arrived onsite, Was unable to find the stormwater intake/ outlet, Went to locate the upstream stormwater manhole in the shrubs and bush using my bar to poke at it as it was buried, Ran water from 5 teme way stormwater lateral and went back down the bank where I could slightly hear water running and found the manhole, Uncovered it and opened the manhole and could see a flow but no dampness or water coming out of the ground where the intake could be. Can I please pass this job into cctv to camera from this stormwater manhole downstream to locate this intake as there maybe a possibility that it maybe piped. The best and easiest way to get to the exposed manhole is going right to the back of 19 Robertson st behind the fence. (Seen in attachments)
				3:40:06 PM		Pass to cctv
				7/13/2022 3:43:12 PM	Reassigned to T/L	Reassigned to T/L . RICH TEXT
				7/15/2022 12:43:31 PM	CCTV Inspection	Arrived on site, accessed through 19 Robertson to manhole to undergo CCTV Inspection to locate intake.
				7/15/2022 12:43:32 PM	Status Change to PAUSE	Team lead to review footage
				7/19/2022 11:17:53 AM	CCTV Notes	19/07/22 CCTV drain section SW007856 to SW015423.TV:3184:59. Intake is located under deck -</td

<u> </u>	T									1	
									8/4/2022	Note from Council	Hi,
									11:51:10		
									AM		Could you let me know if this stormwater markout has
											been completed please?
											Regards,
											Associate - Planning
											SpencerHolmes Limited
											DO Boy E99 Wallington 6140
											PO Box 588, Wellington 6140 Level 10, 57 Willis Street, Wellington 6011
											adg@spencerholmes.co.nz <mailto:adg@spencerholmes.< td=""></mailto:adg@spencerholmes.<>
											co.nz>
											www.spencerholmes.co.nz <blocked::http: td="" www.spenc<=""></blocked::http:>
											erholmes.co.nz/>
											P M M
											Please consider the environment before printing this
											email.
											This email message and any attachments should be
											treated as CONFIDENTIAL. If you are not the intended
											recipient, any use, disclosure or copying of this message
											or attachments is strictly prohibited. If you have received this email message in error please notify
											admin@spencerholmes.co.nz <mailto:admin@spencerho< td=""></mailto:admin@spencerho<>
											Imes.co.nz> immediately and erase all copies of the
											message and any attachments.
									9/15/2022	Email sent to	in attachments RICH TEXT
									10:32:14	homeowner of	
									AM	finding	
										No response from	
									1.43.03 PIVI	homeowner, closing job	
									11/20/2022	Note from Council	Closed by WCC
									2:40:51 PM		,
										CAR N/A no	CAR N/A no excavation RICH TEXT
									7:38:02 AM		
WCCSR-565831		Fault 3a Frobisher Street,	<div>Water leak coming from the street and seems like</div>	Potable	3 CL0		/2023	2/20/2023 2:50:22	2/1/2023	Note from Council	Ticket response email sent to requester due to WWL
	Selected	Island Bay	but is under the ground, as the leak has come into his house and started leaking into the room downstairs			10:10 AM	10:36	PM	10:10:47 AM		managing complaints after initial report to council. Kia ora
			please access <div><div><div><div></div><!--</td--><td></td><td></td><td>Alvi</td><td></td><td></td><td>Aivi</td><td></td><td>Thank you for reporting this water and drainage issue to</td></div></div></div>			Alvi			Aivi		Thank you for reporting this water and drainage issue to
			RICH TEXT>								us.
											The repair of water and drainage issues are managed by
				·			- 				

						Wellington Water. We have passed this details of this fault through to them.
						If you need more information including when this fault will be repaired please call Wellington Water on 04 912 4470 (Monday to Friday 7am – 5pm) or email
						customer@wellingtonwater.co.nz
						Ng? mihi
						Customer Services Wellington City Council
				2/1/2023 10:10:47 AM	Note from Council	Address: 3A FROBISHER STREET, Island Bay Open in Google Maps: https://www.google.com/maps/search/?api=1&query=-41.343611598497596,174.76202798362166
				2/1/2023 10:16:40 AM	Note from Council	Called through to WW
				2/1/2023 10:16:40 AM	Note from Council	Called through to WW
				2/1/2023 10:42:01 AM	Assigned to	Assigned to . RICH TEXT
				2/1/2023 12:40:01 PM	Downgrade to P3, non urgent job	Upon arrival, couldn't get ahold of the resident at 3A as they didn't seem to be home, but the neighbour graciously explained to me that there was water seeping underneath 3A's deck and it was coming from behind the retaining wall. I went and had a look and from what I could see, there was some lifted deck and underneath it was the water.
						Investigating this water, it looks like still water as there isn't any flow or movement in it, and it doesn't seem to be fresh as the water inside is clear, indicating it has been sitting there for a while to allow the mud and dirt to settle in the water.
						The service to the property outside is impossible to access at the time as there was a vehicle parked on top of the manifold but listening to the service in the road and the main, including the service after the toby, sounds to me to be very quiet. There is also no water leaks showing up anywhere from the main or the service feed to the effected area at the house. All of this leads me to believe it is likely to be just ground

					water that has shown up from the recent heavy rain, but I cannot confirm this until the rain stops for long enough that I'm able to take a sample without the sample being contaminated.
					Alternatively, I could pass this job to as it isn't anything from the council side of things as confirmed by the noise testing and visual inspections. However, I will be placing this job on pause until then and request this job be do escalated to a R2 as what has
					and request this job be de-escalated to a P3 as what has been happening doesn't constitute a P1 job and no damage or risk of collapse has happened by this still water
			2/1/2023 12:50:20 PM	Customer called for update	Customer called for update - advised its with our crew member and they have yet to update the file with notes so likely still attending RICH TEXT
			2/1/2023 12:52:53 PM 2/2/2023	downgraded to P3 advised by He is stil investigating customer phoned to	downgraded to P3 advised by He is stil investigating RICH TEXT customer phoned to follow up on job. job closed by
				follow up on job. job closed by accident.	accident Customer is wanting an update advised notes from crew. Customer is thinking the water is coming from the road. RICH TEXT
			2/2/2023 3:28:58 PM	2/2 Awaiting for powerco plans	<pre><div>2/2/23 KT - Plans attached, Caution: There is High Capacity and/or Fibre Network in the area provided on the plan(s).</div><div>Caution: There is Core Network in the area provided on the plan(s).</div><div> /></div><!-- RICH TEXT--></pre>
			2/2/2023 10:12:35 PM	Note from Council	Hi, This ticket has not been resolved and I have spoken to Wellington Water.
					They have re-opened the job and are waiting on an engineer to assess the fault.
					Regards,
					On Thu, Feb 2, 2023 at 2:49 PM Wellington City Council Support < customerservice@wellingtoncitycouncil.freshservice.co m> wrote:
					> Kia ora

 <u></u>	T			
				> Our staff have indicated that this ticket has been
				resolved.
				>
				> Take the survey
				>
				http://hiko.wellington.govt.nz/support/surveys/eyJ0eX
				AiOiJKV1QiLCJhbGciOiJIUzI1NiJ9.eyJyZXN1bHRfaWQiOjc
				1MDA0MTA3NDM1LCJvcHRpb25fY291bnQiOjR9.Nyq2Nl
				Ot9yKgY2b8DS5g9gpyvfBVYq8n9dB-
				L38Xkgg/fill_survey>
				>
				> If you believe that the ticket has not been resolved,
				please reply to this
				> email to automatically reopen the ticket.
				> cinal to automatically reopen the ticket.
				> If there is no response from you, we will assume that
				everything is okay
				> and the ticket will automatically close in 48 hours.
				> In third and the many many and
				> Initial customer request
				> Hans Name (Material during a
				> Item Name : Water and drainage
				> Category : External Customer Services
				> Service : Fault
				> Which water type is this regarding? : Drinking water or
				tap water
				> What is the priority? : Urgent
				> Description : Water leak coming from the street and
				seems like but is
				> under the ground, as the leak has come into his house
				and started leaking
				> into the room downstairs please access
				> Incident address : 3A FROBISHER STREET, Island Bay
				> Location : -
				41.343611598497596,174.76202798362166
				>
				>
				> Ng? mihi,
				> Customer Services, Wellington City Council
				>
				> The information contained in this email is privileged
				and confidential and
				> intended for the addressee only.
				>
				> If you are not the intended recipient, you are asked to
				respect that
				> confidentiality and not disclose, copy or make use of
				its contents.
1	1		1	its contents.

			 			> If received in error you are asked to destroy this email
						and contact the
						> sender immediately. Your assistance is appreciated.
						>
						>
						> [#SR-565831]:274477:fs
						>
				2/7/2023	Potentially private	Upon arrival, I found that the address in question was
				2:20:38 PM	leak; Potentially	down a long flight of stairs which sat behind the address
					Ground water.	above which was #3 Frobisher; Both properties are fed
					Further investigation	off seperate manifolds for note.
					needed	
						Went down to the property to investigate the issue but
						nobody was home, however I located the deck which
						the resident has taken a board out to access this water.
						I looked at this water beneath the deck and noticed that
						there was a fair amount of still water sitting beneath the
						deck, in a dug out trench which was under a pvc pipe.
						I went to the road to see if there was any leaks above
						which contributed to this water but there was no leaks
						on this road surface. Furthermore, the services to the
						nearby properties and the main was quiet, which led me
						to believe this water isn't caused by a potable water leak
						on our end.
						I refrained from taking a sample last week as there was
						a couple days of heavy rain before I arrived and I feared
						it would contaminate the sample, and it was likely that
						this still water was caused from the heavy rain.
						this still water was caused from the fleavy rail.
						As of today (Tuesday 7th February) I returned as there
						was a number of sunny days and this water is still
						underneath the deck and hasn't seemed to dissipate.
						I listened to the services again to ensure I was correct in
						my initial assessment and I still heard no noises on our
						assets.
						With this, I took a 10ml chlorine sample of the water
						and the immediate results returned negative for
						chlorine, however 10 minutes have passed and this 10ml
						sample is now showing a clear pink, showing that it is a
						heavily diluted potable water coming from a source a
						fair distance away.
						As stated before, the services to the nearby address's
						are quiet as well as the main. From all of this
						information, I am unsure how to proceed as to the cause
						of this water and as far as I am concerned, there is no
						issue for Wellington Water assets.

 	 			<u> </u>	
					I shall discuss further action with but until then, this job will be placed on hold pending action
			2/7/2023	Refer to logs and	tine jes will se placed en fleid perianig action
				attachments	
			2/7/2023	Customer called	Customer called wanting update. Advised of below
			3:57:14 PM		notes from Customer is having to spend each night
					emptying buckets of water from under deck. Carpet in
					room is wet. Has had to contact insurance due to this.
					Advised will follow up with TA. Customer to resend
					email for customer email address. RICH TEXT
			2/7/2023	Note from Council	This ticket has not been resolved.
			5:09:27 PM		
					Water is still leaking on Frobisher street through 3b to
					my property 3a
					Frobisher Street.
					I have notified Wellington Water and they are waiting
					on a technician to
					look at it.
					On Tue, 7 Feb 2023 at 2:39 PM, Wellington City Council
					Support <
					customerservice@wellingtoncitycouncil.freshservice.co
					m> wrote:
					> Kia ora
					>
					>
					> Our staff have indicated that this ticket has been
					resolved.
					>
					> Take the survey
					>
					http://hiko.wellington.govt.nz/support/surveys/eyJ0eX
					AiOiJKV1QiLCJhbGciOiJIUzI1NiJ9.eyJyZXN1bHRfaWQiOjc
					1MDA0MTM3MTE5LCJvcHRpb25fY291bnQiOjR9.GHW3
					8ve- WfZS0aeyYmYrcMiwb_gvQRTg6VUvrfyDskI/fill_survey>
					vvizsodeyfiiffciviiwb_gvQkTgovOviTyDski/fiii_survey>
					<u></u>
					> If you believe that the ticket has not been resolved,
					please reply to this
					> email to automatically reopen the ticket.
					>
					> If there is no response from you, we will assume that
					everything is okay
					> and the ticket will automatically close in 48 hours.

						>
						> Initial customer request
						>
						> Item Name : Water and drainage
						> Category : External Customer Services
						> Service : Fault
						> Which water type is this regarding? : Drinking water or
						tap water
						> What is the priority? : Urgent
						> Description : Water leak coming from the street and
						seems like but is
						> under the ground, as the leak has come into his house
						and started leaking
						> into the room downstairs please access
						> Incident address : 3A FROBISHER STREET, Island Bay
						>
						https://www.google.com/maps/search/3A+FROBISHER
						+STREET,+Island+Bay?entry=gmail&source=g>
						> Location : -
						41.343611598497596,174.76202798362166
						>
						>
						> Ng? mihi,
						> (46. (11111))
						> Customer Services, Wellington City Council
						> customer services, weinington city council
						> The information contained in this email is privileged
						and confidential and
						> intended for the addressee only.
						> internaca for the addressee only.
						> If you are not the intended recipient, you are asked to
						respect that
						> confidentiality and not disclose, copy or make use of
						its contents.
						> If received in error you are asked to destroy this email
						and contact the
						> sender immediately. Your assistance is appreciated.
						> selluci illilliculately. Toul assistance is appreciated.
						> [#SR-565831]:274477:fs
						> [#3N 303031].274477.13
				2/8/2023	Passed to TA	Passed to TA as per RICH TEXT
				11:49:14	T d35Cd to TA	ds per district 12x1 >
				AM		
				2/17/2023	customer called in	customer called in wanting a update, I advised him it is
				11:14:54	wanting a update	been assigned to our TA and i would follow up with him
				AM	Wanting a apaate	about this job, I have emailed about this RICH</td
				/ (()		TEXT>
				1		1001

									2/20/2023 2:49:59 PM 2/23/2023 3:46:31 PM	sample result returned 20/02/23. negative Note from Council	sample done has returned a negative result. i have rung and informed him of the result 20/02 1440 RICH TEXT Closed by WCC
					8 Frobishe	r Street			3.40.31 TW		
8 Frobisher Street, Island Bay, Wellington, 6023	WO-269104	No Asset Selected	RWL Private Leak: 8 Frobisher Street, Island Bay	<pre><div>Private leak heard on toby on 22/12/2022. 6LPM Not visible.</div><div><div><div><18/04/2023 HJR - I have sent out the first letters to 8 / 8A / 8B / 8C as this is a shared service</div><div><div><div><22/05/2023 HJR - Sent out the second ss letter </div><div><div><div><08/06/2023 HJR - has been out and we can confirm that 8 A has a 23 LPM and 8 B has a 6 LPM on site </div><div><div><div><12/06/2023 HJR - I have sent out the second SS letter </div><div><div><div><12/06/2023 HJR - I have</div></div></div></div></div></div></div></div></div></div></div></pre>	Potable	4	APPR	12/23/2022 11:40:07 AM	12/23/2022 11:42:02 AM	RWL LDS Notes	Private leaks heard on middle and right hand tobies of 8a,b,c,d. no identification on which tobies belong to which house. RICH TEXT
				sent out the SS letter RICH TEXT					3/10/2023 8:52:48 AM	RWL Team Notes	RWL have rechecked the site and have found there are only two private Leaks. 8A: Large 8LPM at the bottom of the driveway closer to the Tobies in an old repair path, small blue mark. 8B: has a small 3Lpm leak close to the house OR is internal. Both properties will need private leak letter sent to the owners. 8 & Don't have any private leaks at time when checked RICH TEXT
									4/18/2023 3:15:21 PM	18/04/2023 HJR - I have sent out the first letters to 8 / 8A / 8B / 8C as this is a shared service	18/04/2023 HJR - I have sent out the first letters to 8 / 8A / 8B / 8C as this is a shared service RICH TEXT
									5/30/2023 7:51:38 AM	Notes Updated From	<pre><div>Notes Updated From</div></pre>
									300 100	22/05/2023 HJR - Sent out the second ss letter	
									6/9/2023 8:49:26 AM	08/06/2023 HJR -	08/06/2023 HJR - has been out and we can confirm that 8 A has a 2 LPM and 8 B has a 6 LPM on site RICH TEXT
									6/15/2023 11:35:25 AM	12/06/2023 HJR - I have sent out the second SS letter	



				7/3/2023	03/07/2023 HJR - I	
				3:31:16 PM	Have sent out the SS	
					letter	
				7/11/2023		
				7:32:55 AM		
_				7/11/2023	11/07/2023 Updated	<pre><div>08/06/2023 HJR - has been out and we can</div></pre>
				7:46:48 AM	Information	confirm that 8 A has a 21 LPM and 8 B has a 6 LPM on
						site <div></div> <div><div><div><</div><!-- RICH TEXT</td--></div></div>
						>
				7/11/2023		08/06/2023 HJR - has been out and we can
				7:47:10 AM	has been out	confirm that 8 A has a 23 LPM and 8 B has a 6 LPM on
					and we can confirm	site RICH TEXT
					that 8 A has a 23	
					LPM and 8 B has a 6	
					LPM on	



TRUEBRIDGE CALLENDER BEACH

OFFICES: WELLINGTON AUCKLAND HAWKES BAY WAIRARAPA



SURVEYORS ENGINEERS LAND PLANNERS RESOURCE MANAGERS

3 February 2005

Attn:

Subdivision Compliance Group Wellington City Council PO Box 2199 Wellington

4 FRANKMOORE AVE

JOHNSONVILLE

PO BOX 13 142

WELLINGTON 6032

NEW ZEALAND

tcb@tcb.co.nz

www.tcb.co.nz

TEL (04)478 0342

FAX (04)478 9416

SR 112100: LOTS 1 & 2 BEING SUBDIVISION OF LOT 2 DP 341775, FROBISHER STREET

Further to the 223 certification that was granted on 13 January 2005, we now write to request for your certification pursuant to Section 224(c) of the RMA 1991 for the subdivision described above.

With respect to the conditions of consent in your notice of decision, we comment as follows:

- a) The survey plan conforms to the subdivision consent proposal as shown on TCB plan 03-541-001 Rev A.
- b) Enclosed is a cheque for the development impact fee.
- c) No drainage requiring as-built plans to be submitted to the council has been constructed.
- d) The new residential building has been constructed in accordance with the approved plans. Note also that the construction of the external cladding and roof are now completed.
- e) The private driveway within the private property is now completed and is now ready for inspection.
- f) Separate water connection has been constructed to provide for the 2 new allotments.
- g) All water supply pipes passing through a new lot, to serve another lot being created by the subdivision, have been laid wholly within an associated right of way or easement as listed on the memorandum of easements.







- h) Each allotment has been provided with stormwater connection.
- i) Each allotment has been provided with sewerage connection.
- j) Right of way; water supply, private stormwater, sanitary sewer drain easements has been reserved to serve Lot 2 as listed on the memorandum of easements.

Enclosed is our client's cheque for the total of

Development Impact Fee

224 Certification Fee

Total:

Having satisfied Council's Conditions we now await the issue of the Certificate pursuant to the requested certifications.

Please contact the writer if you have any queries regarding this request.

Yours faithfully,

Truebridge Callender Beach Ltd

Surveyor

035411e011.doc

Schedule / Memorandum

16 December 2004

PREPARED BY:



Licensed Codastrol Surveyor
Truebridge Callender Beach
4 Frankmoore Avenue
Johnsonville
PO Box 13 142
Wellington 6032
Tel: (04) 478 0342
Fex: (04) 478 9416
Web: www.tob.co.nx

Land Registration District

Plan Number


Wellington

DP 346714

Territorial Authority (the Council)

Wellington City

Memorandum of Easements (Pursuant to s243 Resource Management Act 1991)								
Purpose	Shown	Servient Tenement	Dominant Tenement					
RIGHT OF WAY WATER SUPPLY STORMWATER SEWAGE DRAINAGE	A	LOT 1	LOT 2					
RIGHT OF WAY WATER SUPPLY STORMWATER SEWAGE DRAINAGE	В	LOT 1	LOT 2					
STORMWATER & SEWAGE DRAINAGE	В	LOT 1	LOT 1 DP 341775					
STORMWATER & SEWAGE DRAINAGE	С	LOT 1	LOT 1 DP 341775					



Construction:

(d) In order to mitigate the potential adverse effects that may arise from creating vacant allotments that do not have the ability to accommodate residential buildings in accordance with the permitted activity conditions of the District Plan, the new residential building proposed for Lots 1 and 2 must be constructed in accordance with the plans approved by condition (a), Decision 1 above prior to the issue of the section 224(c) certificate.

Note:

In order to satisfy condition (d) above, the residential building is to be constructed to a stage where the external cladding and roof are completed.

(e) The private drive within the private property must be constructed. All construction shall be completed generally in accordance with approved construction plans. The construction must include the area contained in right-of-way Areas A and B, as shown on TCB plan No. 03-541-001, Rev. A.

Water Supply:

(f) Each allotment must have a separate water connection to the public water main.

Note:

An application for the new water supply connection should be made to WCC Water Supply.

(g) No water supply pipe(s) shall pass through a new lot, or cross a proposed boundary between lots, to serve another lot being created by the subdivision, except where it is within an associated right of way or access lot.


The Surveyor shall certify in writing that, at the time of certification, this has been achieved. (see E.1.1.2 & E.1.7.2.3 of the Code of Practice)

Sewerage / Stormwater:

- (h) Each allotment must be provided with a stormwater connection to a gravity stormwater system connected to an existing public stormwater drain or other approved outfall. All construction must be completed in accordance with approved construction plans, as required by condition (c) above.
- (i) Each allotment must be provided with a sanitary sewer connection to a gravity sewer system connected to an existing public sewer drain. All construction must be completed in accordance with the approved construction plans, as required by condition (c) above.

Legal:

(j) The right of way, water supply, private stormwater & sanitary sewer drain easements required to serve Lot 2 that are located within Lot 1 are to be duly granted and reserved.



S.R.105548

8 A Frobisher Street SR 112100 Water Supply Conditions 19/3/2004

Water Supply easements will be required where water services cross lots that they do not serve.

SC 262 The estimated cost is including G.S.T

SC212 Happy Valley Water Supply Zone Contribution Figure including G.S.T for one new unit



18 February, 2004



Compliance Monitoring Team Urban Strategy Group Wellington City Council P O Box 2199 WELLINGTON

RE: SR: 105548

SUBDIVISION OF 8 FROBISHER STREET

I refer to Council's Notice of Decision dated 3 September 2003 granting conditional approval to above subdivision and enclose the Land Transfer title plan for certification pursuant to Sections 223 and 224(c) of the Resource Management Act.

In respect of the conditions imposed I advise that these have been complied with as follows:

- a) The survey plan conforms with the subdivision consent proposal shown on plan numbered 4021/5 except in respect of the right of way which was amended and approved by letter of 9 January 2004.
- b) A receipt for the development impact fee of
- c) Engineering plans for vehicle access were not necessary as the driveway is already constructed. New private drains have been laid down the centre of the driveway to service the new Lot 2. As built plans of the private drainage are enclosed.
- d) In respect of the construction of the driveway refer to comments in (e) above and my letter of 19 December 2003.
- e) The existing garage within the proposed Lot 2 has been removed.
- f) The water connects fee has been paid and both the service pipe and toby and the supply pipe to Lot 2 installed. A receipt is enclosed.
- g) I hereby certify that no water supply pipes pas through a new lot, or cross a proposed boundary between lots, to serve another lot being created by the subdivision, except where it is within an associated right of way.



PO Box 17-376, 272 Karori Road, Wellington

Phone: 64 4 476-7499 Fax: 64 4 476-5927

Email: enquiries@maundersurvey.co.nz

C:\My Documents\Mail\4000-4499\4021h.doc www.maundersurvey.co.nz

112208

h) Easements for rights of way, private drainage and water supply have been included in a Memorandum of easements on the land transfer plan.

As Lot 2 does not possess legal frontage, would you please issue a section 321 certificate to be registered against the certificate of title for this lot.

A copy of the plan is enclosed for your records. Enclosed is a cheque for the certification fee.





constructed within each of proposed Lots 1 and 2. Both proposed townhouses are two storey and are attached via a shared internal wall along the internal subdivision boundary.

The proposed new dwellings are of modern design and have areas available for outdoor living in the form of decks.

Both of the proposed new dwellings have two bedrooms, bathroom and entrance area on the lower level and study, kitchen, dining/living area and deck on the upper level. Please refer to the Dwelling Plans attached at Appendix Five.

2.1.1 Access - Roads

As outlined above, both allotments will be accessed via a shared entrance and right of way from Frobisher Street.

2.1.2 Water Supply

As part of the previous subdivision development a new water service and toby is to be laid to service the two new townhouses within proposed Lots 1 and 2. The individual sites will be connected as a requirement of the subdivision. Both allotments will be connected to water supply in accordance with the requirements of the Council's Code of Practice for Land Development.

2.1.3 Sanitary Sewer

Sanitary sewer connections will be provided to the proposed allotments in accordance with the Code of Practice. As part of the previous subdivision development sewage will be piped via a new drain to the existing drain in Frobisher Street and both allotments will be connected as a requirement of the subdivision.

2.1.4 Stormwater

As indicated above and as a requirement of the previous subdivision, stormwater will be piped via a new stormwater drain to the existing street channel. Both allotments will be connected to the existing stormwater system as a requirement of the subdivision.

Water Supply Conditions – SR105548 – 8 Frobisher St 26/08/03

• Water fees – Happy Valley / Frobisher Zone

per household unit or new allotment created.

2 Townhouses = - Not bung tonstructed

SC262 Lot 2 (14m) incl. GST.

Each unit shall have its own water shut valve so that it can be isolated individually from the water supply.

SC263

SC363 Water easement x=2, y=1.

5.1.1.2 Site Access

Access to both Lots would be via the existing concrete driveway over Lot 1 with turning space allocated to Lot 1 over Lot 2 and vice versa.

Number of Household Units 5.1.3.1

There would be 1 household unit on Lot 1 and 2 on Lot 2. Construction of the two units on would not commence until the subdivision is completed and new certificates of titles issued.

5.1.3.2 Yards

There would be no breach of vard as a result of the subdivision.

Site Coverage

Lot 1. The 'site area' for Lot 1 would be 605m² and total building coverage would be 151.5m2 or 25%.

Building Height 5.1.3.4

Existing and proposal buildings would not exceed 8m in height.

Sunlight Access 5.1.3.5

Lot 1. The proposed garage on Lot 1, would be clear of the sunlight access planes. Refer Architects drawing.

The existing house would encroach through Sunlight Access Plane on the new Lot 1/2 boundary. Although this is on the gable end of the house, the pitch of the roof is 20%, therefore gable end dispensation does not apply. The encroachment would be 1.67 at the ridge line and 0.54 on the western eave land use consent is sought for this encroachment.

Lot 2. The proposed units on Lot 2 would not encroach though the sunlight access planes generated on the peripheral nor the new Lot 1-2 boundary. The new building would have a hip roof with gutters, level at least 1.1 below the SAP on the 1-2 boundary.

5.1.3.6 Maximum Fence Height

No new boundary fences would exceed 2.0m.

2.1.3 Compliance with the Subdivision Design Guide

The Design Guide places emphasis on the amenity value and quality with the intention to make residential areas better places to live in. As this subdivision proposal is for an infill subdivision erecting no new roads or public space and having no effect on public amenity on assessment under the Subdivision Design Guide has not been prepared.

Compliance with the Code of Practice for Land Development 2.1.4

The matters to be considered under the Code of Practice include water supply, vehicle parking and access, drainage and earthworks.

Water Supply 2.1.4.1

Lot 1. The existing water service and supply pipe will continue to supply water to the existing house.

PO Box 17-376, 272 Karori Road, Wellington

C:\Documents and Settings\Sylvia Maunder\My Documents\RCApps\4021app.doc
Phone: 64 4 476-7499 Fax: 64 4 476-5927 www.maundersurvey.co.pz

Email: enquiries@maundersurvey.co.nz

Lot 2. A new water service and toby is to be laid for the new town houses on Lot 2.

2.1.4.2 Vehicle Parking and Access

Please see 2.1.2 above.

2.1.4.3 Drainage

Stormwater

Lot 1. Roof water is piped to the kerb and channel in Frobisher Street and picks up the runoff from the drive which is collected in a sump on Lot 1. An easement will protect the drain where it crosses in to Lot 2.

Lot 2. Roof water would be piped via a new stormwater drain to the street channel. An easement will protect this drain through Lot 1.

Sewage

Lot 1. Sewage is piped to the public drain in Frobisher Street. An easement would be created to protect this where it crosses the Lot 2.

Lot 2. Sewage would be piped via a new drain to the public drain in Frobisher Street. An easement will protect the drain through Lot 1.

2.1.4.4 Earthworks

A By-Laws earthworks consent will be required to construct the turning areas for Lots 1 and 2 and construct the garage on Lot 1. The maximum depth of excavation would be 1.0m.

ASSESSMENT 3

The proposal is consistent with the objectives policies of the District Plan and the effects on the environment as a result of granting subdivision consent would be less than minor.

The only aspect of non compliance with the District Plan Rules is the sunlight access plans encroachment on the new Lot 1/2 boundary and this is within the discretionary limits and is also consented to by the applicant.

SECTION 321 CERTIFICATE 4.

Because Lot 2 would not have frontage to a legal road a Section 321(3)(c) certificate should be issued for this new allotment.



PO Box 17-376, 272 Karori Road, Wellington C:\Documents and Settings\Sylvia Maunder\My Documents\RCApps\4021app.doc www.maundersurvey.co.nz

Phone: 64 4 476-7499 Fax: 64 4 476-5927

5.1.3.1 Number of Household Units

There would be one household unit per site.

5.1.3.2 Yards

All yard requirements would be adhered to.

5.1.3.3 Site Coverage

Both allotments are within the site coverage rules Lot 1 would have 32% building coverage and an extra 8% deck coverage, and lot 2 would have 17% building coverage

5.1.3.4 Building Height

No building shall exceed the 8 metre height limit.

5.1.3.5 Sunlight Access

Both dwellings are within the sunlight access planes on all boundaries.

5.1.3.6 Maximum Fence Height

No fence is to be erected within 1 metre of any new boundary that would exceed the 2 metre height limit.

2.1.3 Compliance with the Subdivision Design Guide

The Design Guide places emphasis on the amenity value and quality with the intention to make residential areas better places to live in. Due to the nature of this in-fill subdivision, there is no impact on public space as a result of this subdivision, and an assessment under the subdivision design guide is not required.

2.1.4 <u>Compliance with the Code of Practice for Land Development</u> The matters to be considered under the Code of Practice include water supply, vehicle parking and access, drainage and earthworks.

2.1.4.1 Water Supply

Both dwellings will be serviced by the water main in Frobisher Street. Lot 1 will have a water easement within the right of way over lot 2.

2.1.4.2 Vehicle Parking and Access

Both allotments would have on site parking, and would have access to Frobisher Street via the existing driveway. Refer 2.1.2 above.



PO Box 17-376, 272 Karori Road, Wellington

Phone: 64 4 476-7499 Fax: 64 4 476-5927

Email: peter.maunder@asiaonline.net.nz