


## Porirua Wastewater Treatment Plant performance - October 2025

| Commentary                                   | Discharges                            | Odour Complaints                | Items of significance   | Current status |   |
|--|---------------------------------------|---------------------------------|---|----------------|---|
| The plant is compliant for effluent quality. | No unconsented discharges in October. | No odour complaints in October. | <p>On 16 October the Duron UV system faulted, however, due to low flows during the early hours of the morning this did not lead to an unconsented discharge. The plant is running the backup TAK UV system as duty during night hours and weekends until the fault can be fixed. This duty switch has been successful during previous Duron faults and is reliable mitigation for ensuring continuous UV disinfection until the Duron unit is reliably repaired.</p> <p>The UV manufacturer is currently working through various options with the plant operator to identify and fix the fault as soon as possible.</p> | Compliant      |  |