

Friday 24 February 2023

OIA IRO-370

Name:

Email: @gmail.com

Kia ora

Official information request regarding job undertaken at 15 Bloomsbury Grove, Newlands.

Thank you for your official information request dated Wednesday 21 December 2023.

We have considered your request in accordance with the Local Government Official Information and Meetings Act 1987 and determined that we are able to grant your request in full.

The information you have requested is enclosed in our email to you. We can confirm that as at the date this job was closed, no further action was required.

Some of the information within the Job Sheets provided has been redacted pursuant to Section 7(2)(a) as it personal information about private individuals.

You have the right to seek an investigation and review by the Ombudsman of this decision. Information about how to make a complaint is available at www.ombudsman.parliament.nz or freephone 0800 802 602.

Ngā mihi

Team Lead, Communications and Engagement

For the latest news and updates, follow us on our social channels:



/wellingtonwater



@wgtnwaternz & @wgtnwateroutage



@wellington_water



Service Request Data – OIA IRO-370 Job Sheet (Page 1)

| council_ name | water_type | request id | request_type | comm_description | Day of created | status | Day of closed | address | Priority | allocation | responsibl e_user | details | Data_Source | id asset | asset id | asset_description | |
|------------------|------------|--------------|---------------|------------------|----------------|----------------------|----------------|--|----------|--------------------------------|----------------------|--|-------------|----------|------------------|---------------------------------|-------|
| Grand Total | Total | Total | Total | Total | Total | Total | Total | Total | | Total | Total | Total | Total | Total | Total | Total | 4 |
| PCC | Water | WCCSR-482238 | | General Fault | 02 Nov 2022 | 90 closed (close) | | 15 bloomsbury grove, newlands, wellington, 6037 | | 007-WGTN-PW-RETC- CONN-VALV | | Fault 2/15 Bloomsbury Grove, Newlands (ROVER) | Maximo | 369097 | WCC_PW01 4538 | Wcc_pw014538 valve ball 20mm | 1 |
| | | WCCSR-485115 | System faults | Leaking Pipes | 06 Nov 2022 | 90 closed (close) | 18 Nov 2022 | 15 bloomsbury grove, newlands, wellington, 6037 | P2 | 007-WGTN-PW-RETC | | Leaking Pipes 15 BLOOMSBURY GROVE, Newlands | Maximo | | | | 1 |
| | | | | | | | | | | | | | | | | | |
| | | · | | | | · | | | | | | | | | | | \pm |
| | | | | | | 4 | | | | | | | | | | | |