

Wellington Metropolitan Water Treatment Plants Monthly Performance Report

September 2025

Month/Year September 2025

Water Treatment p	Comments		Safe Drinking Water	Fluoride
Waterloo	Naterloo WTP is non-compliant with the Water Services Authority bacterial compliance rules*. This issue does not affect drinking water safety. The WTP is compliant with the Authority's Protozoal compliance rules. Naterloo fluoridated the drinking water within MoH's recommended levels 97.8% of the time.			
Wainuiomata	Wainuiomata WTP is compliant with the Water Services Authority bacterial and protozoal compliance rules. Wainuiomata has fluoridated the drinking water within MoH's recommended levels 92.4% of the time. The low level was due to planned and reactive treatment plant shutdowns and maintenance. The WTP was shut down while the Flexitend couplings were installed at Rocky Point.			
Te Mārua	Te Mārua WTP is compliant with the Water Services Authority bacterial and protozoal compliance rules. Construction of the new Powdered Activated Carbon dosing plant is currently underway. The Filter 3 media replacement project is progressing well. Te Mārua has fluoridated the drinking water within MoH's recommended levels 98.4% of the time.			
Gear Island	Gear Isl WTP is compliant with the Water Services Authority bacterial and protozoal compliance rules. Gear Island has fluoridated the drinking water within MoH's recommended levels 93.7% of the time. The low level was due to planned shutdowns and asset maintenance A significant leak was found on the 1050 main, on the western side of the Hutt Park Bridge, which meant shutting down the Gear Isl WTP.			
layout of the network, a significant treatment plant upgrade and/or additional network infrastructure is required to		Compliant – we are meeting the necessary regulatory requirements Not compliant but nearing compliance Not compliant with necessary regulatory requirements	Fluoride Complia	ance (% Monthly)



Fluoride Compliance (% Monthly)







Month/Year

To Null

Note:

The bar graph displays the fluoride monthly compliance from January 2025. The blue bars represents the fluoride percentage compliance each month.

Our aim is to maintain a steady fluoride level in the water that meets the Ministry of Health's recommended levels no less than 95%, represented by the red dotted line in the graph. The recommended compliance percentage area is shaded light green, while areas outside this are shaded light red to indicate non-compliance.

Te Mārua



Gear Island

